



EUROPEAN YACHTING NETWORK

Middelzee Kruiser 1390 AK (1974)

Property: 64.804.2562



EYN Price: € 0

Length: 13,60 m; Width: 4,00 m; Draft: 1,20 m; Headroom: 2,00 m; Engine brand: Perkins ; Total engine power: 150 hp; Engine hours: 670 hour; Number of engines: 1 ;



EUROPEAN YACHTING NETWORK

The yacht

Brand	Middelzee
Type	Kruiser 1390 AK
Boat type	Motor boat
Name of the boat	Aloha
BTW/VAT	Paid
Year of construction	1974
Berth	Limburg - Nederland

Sizes & Weights

Length	13,60 m
Width	4,00 m
Draft	1,20 m
Clearance	3,40 m
Headroom	2,00 m
Drinking water	1.000 l
Black water	250 l

The engine

Engine brand	Perkins
Total engine power	150 hp
Engine hours	670 hour
Last service	-
Fuel tank capacity	1.000 l



EUROPEAN YACHTING NETWORK

DECK EQUIPMENT

Material deck	Steel
Anchor	ja
Options present	Swimming ladder Swimming platform Rail Deck washing system Bimini top Spray hood Anchor winch Sailing lights Davits Dining table

ELECTRONICS

Voltage circuit	12V + 24V + 220V
Heating	Central heating
Options present	Washing machine Solar panels Battery charger 2x Victron 70A Shore power

ENGINE ROOM

Number of engines	1
Fuel	Diesel
Generator	yess Kohler 3,5Kva Diesel
Options present	220V socket Bilge-pump Converter 2x 3000W Water pressure system Boiler 80L 230v+motor

ENTERTAINMENT

Options present	Sound system
------------------------	--------------



EUROPEAN YACHTING NETWORK

GALLEY

Cooking ring	Keramisch
Options present	Oven Microwave Sink Freezer Fridge

INTERIOR LAYOUT

Berths	4
Bedrooms	1
Window frames	Aluminium
Bathroom	1
Options present	Aft cabin

MATERIALS INTERIOR

Ceiling	Wood
----------------	------

NAVIGATION

Bow thruster	Electric
Heck thruster	Electric
Rudder Indicator	yes
Options present	Mariphone Log Depth gauge Claxon

OTHER

Options present	Fenders
------------------------	---------

SAFETY

Options present	Fire extinguisher(s)
------------------------	----------------------

TECHNICAL DETAILS



EUROPEAN YACHTING NETWORK

Type of engine	Inboard
Technical condition below the waterline	Good condition (painted 2016)
Propulsion	Grease lubricated shaft
Propeller(s)	4 Blades
Material (hull)	Steel
Type of boat	Motorboat
Type of hull	Chine
Sailing properties	Displacer
Material structure	Steel
Technical condition hull	Good condition
Technical condition deck	Good condition (needs Paint)
Condition structure	Good condition (needs Paint)
Options present	Second Steering console

WET ROOM

Toilet	1
Shower	1



EUROPEAN YACHTING NETWORK





EUROPEAN YACHTING NETWORK





EUROPEAN YACHTING NETWORK

