

Bayliner 300SB (2008)

Property: 64.611.2395



EYN Price: **€ 0**

Length: 9,30 m; Width: 3,05 m; Draft: 0,80 m; Headroom: 1,90 m; Engine brand: Mercruiser 4.3L MPI; Total engine power: 440 hp; Engine hours: 100 hour; Number of engines: 2; -: Shipyard;

Very well maintained Bayliner with very low running hours. The boat is in top condition with almost no traces. Various options are available such as a stainless steel anchor with electric winch, Searchlight, bow thruster, Jensen audio package, chrome portholes and a Bravo III drive. Original CE, VAT Payed For more information, please contact your broker, Charles Clabbers +31-6-51412631 / Zuidboten@e-y-n.com



The yacht

BrandBaylinerType300SBBoat typeMotor boatName of the boatMe Gusta

BTW/VAT Paid
Year of construction 2008

Berth Limburg - Nederland

Shipyard Brunswick

Sizes & Weights

Length 9,30 m Width 3,05 m Draft 0,80 m **Displacement** 4.127 kg Headroom 1,90 m **Drinking water** 124 l **Black water** 113 l **Maximum speed** 35 kn 22 kn **Cruising speed**

The engine

Engine brand Mercruiser 4.3L MPI

Total engine power440 hpEngine hours100 hourLast service01-04-2016

Fueltank capacity 454 l



DECK EQUIPMENT

Material deckPolyesterAnchorElectrical

Options present Swimming ladder

Swimming platform Shower on aft deck

Cockpitcover

Sun Cushions (deck)

Anchor winch Sailing lights Dining table

Self-draining cockpit

ELECTRONICS

Voltage circuit 12V + 230V Options present Battery charger

ENGINE ROOM

Starting batteries 1 (105Ah)

Type of light batteries Lead

Exhaust Water Cooled

Number of engines 2

Fuel Petrol

Type of starting batteries Lead

Light batteries2 (2x 105Ah)Options present220V socketBilge-pump

Water pressure system

Boiler

ENTERTAINMENT

Options present Sound system

TV

GALLEY



EUROPEAN YACHTING NETWORK

Cooking ring Electric + Alcohol (2P)

Options present Microwave

Sink Fridge

INTERIOR LAYOUT

Berths 6
Bedrooms 2

Options present Aft cabin

Dinette

MATERIALS INTERIOR

Ceiling Synthetic material

- Shipyard

Seats Artificial leather

Options present Curtains

NAVIGATION

Bow thruster ja **Rudder Indicator** yes

Options present Mariphone

Log

Compass
Depth gauge
Claxon
Map plotter

OTHER

Options present Covers, winter

SAFETY

CE-mark B

Options present Gas detector

Sprinkler system



TECHNICAL DETAILS

Type of engine Sterndrive

Technical condition below the Good condition

waterline

Propulsion Z-drive Bravo 3

Propeller(s)

Material (hull)

Polyester

Type of hull

Deep-V

Sailing properties

Planing

Steering equipment

Hydraulic

Material structure

Polyester

Technical condition hullGood conditionTechnical condition deckGood conditionCondition structureGood condition

Options present Bow planes

WET ROOM

Toilet 1 (electric)

Shower 2























