



EUROPEAN YACHTING NETWORK

Valk kruiser 1200 AK / VK (1978)

Property: 16.709.2478



EYN Price: **€ 52.500**

Length: 12,60 m; Width: 3,80 m; Draft: 1,15 m; Headroom: 1,90 m; Engine brand: Ford Lehman 6 cil. diesel; Total engine power: 120 hp; Engine hours: 2.425 hour; Number of engines: 1 ; -: Shipyard ;

In good condition. 3 cabins with 6 berths.



EUROPEAN YACHTING NETWORK

The yacht

Brand	Valk kruiser
Type	1200 AK / VK
Boat type	Motor boat
Name of the boat	Lady Ann
BTW/VAT	Paid
Year of construction	1978
Berth	Noord-Brabant - Nederland
Shipyard	Wim van der Valk

Sizes & Weights

Length	12,60 m
Width	3,80 m
Draft	1,15 m
Clearance	3,00 m
Displacement	12.000 kg
Headroom	1,90 m

The engine

Engine brand	Ford Lehman 6 cil. diesel
Total engine power	120 hp
Engine hours	2.425 hour
Last service	01-09-2016
Fuel tank capacity	0 l



EUROPEAN YACHTING NETWORK

* POSSIBILITIES

Status Reduced in price!

DECK EQUIPMENT

Material deck Steel
Anchor Manual
Options present Swimming ladder
Swimming platform
Rail
Shower on aft deck
Bimini top
Spray hood
Anchor winch
Sailing lights
Davits

ELECTRONICS

Voltage circuit 12V + 220V
Heating yes
Options present Battery charger
Shore power

ENGINE ROOM

Number of engines 1
Fuel Diesel
Options present Washbasin
220V socket
Bilge-pump
Converter

ENTERTAINMENT

Options present Sound system

GALLEY

Cooking ring 4 Burners gas



EUROPEAN YACHTING NETWORK

Options present	Oven
	Geyser
	Sink
	Fridge

INTERIOR LAYOUT

Berths	6
Bedrooms	3
Window frames	Aluminium
Options present	Aft cabin
	Front cabin
	Dinette

MATERIALS INTERIOR

Ceiling	Wood
-	Shipyards
Floor covering	Hout
Woodwork	Mahogany
Seats	Leather
Options present	Curtains

NAVIGATION

Bow thruster	Electric
Heck thruster	Electric
Rudder Indicator	yes
Options present	Compass
	Depth gauge

OTHER

Options present	Fenders
------------------------	---------

SAFETY

Options present	Smoke alarm
	Gas detector
	Fire extinguisher(s)



EUROPEAN YACHTING NETWORK

TECHNICAL DETAILS

Type of engine	Inboard
Technical condition below the waterline	Good condition
Material (hull)	Steel
Steering equipment	Hydraulic
Material structure	Steel
Technical condition hull	Good condition
Technical condition deck	Good condition
Condition structure	Good condition
Options present	Second Steering console

WET ROOM

Toilet	1
---------------	---



EUROPEAN YACHTING NETWORK





EUROPEAN YACHTING NETWORK





EUROPEAN YACHTING NETWORK

