



EUROPEAN YACHTING NETWORK

Waaslandkruiser One Off (1992)

Property: 66.803.2551



EYN Price: **€ 79.000**

Length: 13,35 m; Width: 4,10 m; Draft: 1,15 m; Headroom: 2,00 m; Engine brand: DAF 615; Total engine power: 276 hp; Engine hours: Unknown; Number of engines: 2 ; - : Owner ; Trade: Negotiable ; Rent (to buy): Not possible ; Private Financing: Possible ;

Very nice and spacious Waasland Cruiser for sale Anodes and antifouling will be done in the next weeks. The hull was painted in 2017 (2-components)



EUROPEAN YACHTING NETWORK

The yacht

Brand	Waaslandkruiser
Type	One Off
Boat type	Motor boat
BTW/VAT	Paid
Year of construction	1992
Berth	Oost-Vlaanderen - België

Sizes & Weights

Length	13,35 m
Width	4,10 m
Draft	1,15 m
Clearance	3,30 m
Headroom	2,00 m
Drinking water	650 l
Black water	120 l

The engine

Engine brand	DAF 615
Total engine power	276 hp
Last service	01-03-2018
Fueltank capacity	1.600 l



EUROPEAN YACHTING NETWORK

* POSSIBILITIES

Private Financing	Possible
Berth	Not transferable
Trade	Negotiable
Suitable for habitation	Yes
Rent (to buy)	Not possible

DECK EQUIPMENT

Material deck	Steel
Options present	Swimming platform Rail

ELECTRONICS

Voltage circuit	24v + 220v
Options present	Washing machine Shore power

ENGINE ROOM

Starting batteries	2
Number of engines	2
Fuel	Diesel
Options present	220V socket Bilge-pump Converter Boiler

ENTERTAINMENT

Options present	TV Satellite
------------------------	-----------------

GALLEY

Cooking ring	Gas 4-pits
Options present	Oven Microwave Sink



EUROPEAN YACHTING NETWORK

Fridge

INTERIOR LAYOUT

Berths	3
Bedrooms	2
Bathroom	1
Options present	Aft cabin Front cabin

MATERIALS INTERIOR

Ceiling	Wood
-	Owner
Floor covering	Hout

NAVIGATION

Bow thruster	Electric 6hp
Rudder Indicator	1

OTHER

Options present	Fenders
------------------------	---------

TECHNICAL DETAILS

Type of engine	Inboard
Technical condition below the waterline	Good condition
Material (hull)	Steel
Anti fouling	Done 2018
Technical condition hull	Good condition
Technical condition deck	Good condition
Condition structure	Good condition

WET ROOM

Toilet	1
Shower	1



EUROPEAN YACHTING NETWORK

Bathrooms

1



EUROPEAN YACHTING NETWORK





EUROPEAN YACHTING NETWORK





EUROPEAN YACHTING NETWORK

